



ID 234

Length 4,1 km Travel Speed 35 km/h

Passenger flow Not available

Inauguration 1889

Closure -

Importance ...

... border region Low

... countries concerned Medium

... TEN-T network Low

Status of operation operational Classification 2017 exploited with shortcomings services

TEN-T corridor North Sea - Baltic

Missing infrastructure -

Administrative obstacles -

INTEROPERABILITY ISSUES

Railway gauge 1520 mm

Number of tracks 1

Electrification -

Train control system -

OPERATIONAL ISSUES

Type of service Passenger services Touristic/seasonal services Freight servicesPassenger services in 2017 28 / 0 / 0 / -
regional/long distance/TEN-T/seasonal Number of trains per week (number of operating weeks in brackets)

Infrastructure manager EESTI RAUDTEE [EE]; LDz Infrastruktura [LV]

Language of operation ?

Competent authorities for PSO passenger services MKM [EE]; Satiksmes ministrijas [LV]

Railway undertaking(s) Elron [EE]; LDz [LV]

Ministry of transport MKM [EE]; Satiksmes ministrijas [LV]

ADDITIONAL INFORMATION

Change of trains in Valga is always required, connections generally poor.